


การไฟฟ้าฝ่ายผลิตแห่งประเทศไทย (โรงใต้)

- The Machine is Circulating Water Makeup Pump
- The old system is Bently Nevada model 2201 with “AB” PLC 5
- The Vibration module didn’t work properly, but PLC 5 is still OK.
- The problem is the Bently Nevada system can’t be replaced only by any new model. EGAT must purchase a new whole Bently Nevada system with new PLC.
- The customer contacted us to propose a replacement vibration system to Bently Nevada model 2100 to work with their old PLC 5 to save the cost to replace whole system.
- We propose “AB” XM 161 plus general vibration sensors with splash proof connector, on the condition that the new system must be able to integrate with their existing control system.

AST

New Sensors installation on Circulating Water Makeup Pump








Most Valued Global Provider of Predictive Maintenance Solution

AST







New Vibration online installation in the existing control cabinet

